Approved For Release 2001/04/02: CIA-RDP78B04747A003100030026-7

10 October 1961

MEMORANDUM FOR: Chief, Administrative Staff, NPIC

STATINTL ATTENTION:

STATINTL

SUBJECT:

Correlator

Task Order #2, Image

STATINTL

REFERENCE:

Engineering Memorandum No. 2004-1,

dated 29 September 1961

1. In accordance with the referenced memorandum, it is requested that the optical system of the subject device be supplied with a filtered positive pressure.

2. It is understood that no change of scope is involved with

STATINTL

STATINTL

the above change.

Chief, TP & DS

STATINTL

MPIC/TP&DS

Declass Review by NIMA/DOD

Approved For Release 2001/04/02 : CIA-RDP78B04747A003100030026-7

Տ**երթրում**ed For Belease 2001/04/02 : CIA-RDP78B04747A003100030026-7 29 September 1961 ENGINEERING MEMORANDUM No. 2004-1 Uncl. STATINTL To: Contract Item Central Intelligence Agency Action Required Washington 25, D. C. Telcon Report Meeting Report Subj: Image Correlator Reply Requested Ref: Your recent inquiry The change blocks checked below are intended to indicate areas which may STATINTL Encl: be affected by this EM and do not obligate to make the change, or CONTRACT: the customer to request or authorize it. Change, if any, will be negotiated through separate channels. Released: STATINTL This EM Affects or May Affect: Scope Ch Circuit Design No 🗵 Mechanical Design Yes Logical Design

In answer to your recent query regarding the shutter and exposure time in the image correlator, a slide will be pulled and the lamps flashed for a few seconds. There will be no mechnical shutter.

Drawings Design Data

Delivery

Material & Components

Project Administrator

Contract Administrator

Brame, the Mechanical Engineer, reaffims that it will be a trivial matter to supply filtered air for positive pressure in the optical system.

We have determined that all the mirrors in the correlator have been coated with silicon monoxide.

PCR:cmg